

# GENERAL NOTES

1. ROOF ABOVE SHOP AREA SHOWED MANY SIGNS OF CURRENT AND PAST LEAKAGE.
2. PLASTER CEILING IN SHOP AREA HAS EXTENSIVE WATER DAMAGE.
3. CEILING MATERIALS AND HEIGHTS AS NOTED ON PLAN.

